

No. 98-1

## Date: February 12, 1998

## SUBJECT: Underhood Cooling on Summit X 670

YEAR	MODEL	MODEL NUMBER	SERIAL NUMBER
1998	Summit X 670	1307/1310	All

In order to lower the underhood temperature you may have to remove steel plate and foam behind the consoles, located on each side of the fuel tank.

From the engine side, unscrew plate and foam through holes seen in foam. Refer to following photo.



LEFT SIDE SHOWN

1. Remove plate and foam